
Site Map
North Carolina
Monitoring Well Network
Roseland Site, S 50F
Northwest of Pine Bluff,
Moore County, NC
NOTE: This map is for informational purposes only. It does not authorize any party to enter onto any lands depicted herein.
N
forest
forest
Hoffman Rd
Roseland Rd
Pine Bluff
horse barn
Roseland Monitoring Station (2 wells)
Hoffman ~ 8.3 miles
Shaver Ln
forest
500 ft
Latitude: 35.146261
Longitude: -79.567607
3152 Hoffman Rd
Jackson Springs, NC 27281
gate
B
217.3'
197.6'
S 50F5
monument
S 50F4
193'
213'
A
forest
Hoffman Rd
R10 Monument
Coordinates (03-05-2015)
Latitude: 35.146250
Longitude: -79.567592
Measurements to Monument
S50F5 - monument = 20'
S50F4 - monument = 2.3'
B - monument = 215'
A - monument = 2107'

04-15-2024