


Anyone working on this site must be listed on the Permit and the Permit must be with you at all times
Access to this site is prohibited from December 1 through March 31.

Site Map (Page 1 of 2)
North Carolina
Monitoring Well Network
Clingmans Dome Site, N 97F
Great Smoky Mountains National Park, Swain County, NC



NOTE: This map is for informational purposes only. It does not authorize any party to enter onto any lands depicted herein.




Anyone working on this site must be listed on the Permit and the Permit must be with you at all times. Access to this site is prohibited from December 1 through March 31.

Site Map (Page 2 of 2)
 North Carolina
 Monitoring Well Network
 Clingmans Dome Site, N 97F
 Great Smoky Mountains National Park, Swain County, NC

NOTE: This map is for informational purposes only. It does not authorize any party to enter onto any lands depicted herein.



Clingmans Dome Monitoring Station (1 well)



R10 Monument
 Coordinates (12-09-2015)
 Latitude: 35.564785
 Longitude: -83.493961

Latitude: 35.565060
 Longitude: -83.493660