

Entrance Coordinates

Latitude: 36.37997

Longitude: -79.69467

Site Map


North Carolina

Monitoring Well Network

Upper Piedmont RS Site, D 52L

Rockingham County, NC


NOTE: This map is for informational purposes only. It does not authorize any party to enter onto any lands depicted herein.



Upper Piedmont Research Station

Upper Piedmont RS Monitoring Station (1 well)

Latitude: 36.375486
Longitude: -79.685453



R10 Monument Coordinates (04-15-2015)
Latitude: 36.375508
Longitude: -79.685452

Inactive wells

500 ft